

2583
B- ~~2583~~

MAGI #84258355 04

POPPLETON HISTORIC STUDY

<u>Block</u>	<u>Lot</u>	<u>Address</u>
200	121/122	1100 W. Fairmount Avenue
	111-120	1064-1082 W. Fairmount Avenue.

Approximate age

<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
------------------	------------------	------------------	------------------	----------------

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>	
A	Significant-save	good fair poor bad	1100
B	Quality-Indiv./groups-save	good fair poor bad	
C	Important to street/groups	good fair poor bad	1066-1082
D	Insignificant/detrimental	good fair poor bad	


Notable features:

The group is perhaps late 19th century workers' housing for the mill. Numbers 1062-1066 have gable roofs; the others are flat with cornices. All have 6/6 windows and cellar entrances. Number 1082, probably a former stable, is presently used as a garage.

Photo below shows floor joists laid directly on ground at 1111 W. Fairmount Avenue, where demolition took place during course of this survey.

Environmental context:



This is a quiet pleasant back street with all good houses recently removed from its south side; the rear of the theater and 3 garages plus empty lots are the view across the street. Has potential as quiet residential, but redesign of Baltimore Street will be more important. Lot at 1064 is cleared.



B-2583

1064-1082 & 1100 W. Fairmount Avenue (1064-1082 Demolished)

Sanborn Maps



W FAYETTE ST

N CARROLLTON AVE

FAYETTE-FAIRMOUNT

FAYETTE-FAIRMOUNT

CARROLLTON ALLEY-SCHRAEDER

W FAIRMOUNT AVE

N CARROLL ST

B-2583

GIS data Courtesy of
the City of Baltimore, MOIT/EGIS

